



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah


DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program

Reviewed: 

~~6/4/13~~
12-5-13

Mine Name: Elite West	Permit Number: S/049/0050
Operator Name: Brett Bryson	Inspection Date: 12/5/2013
Inspector(s): April Abate	Time: 10 AM
Other Participants: none	Mine Status: Inactive

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)
8. Soils
9. Revegetation
10. Other

Evaluated Comment Enforcement

<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Permit fee: Not Paid

Bond Renewal Date: 10/10/2008

Bond Amount: \$10,000

Purpose of Inspection:

The Purpose of the inspection was to determine if the operator has begun reclamation at the site. A Division Directive was sent on August 28, 2013 ordering the operator to complete reclamation by September 30, 2013.


Weather: Cold, 22 F

Inspection Summary:

It was difficult to determine if reclamation work has progressed at the site due to snow covering the ground. The front end loader that was observed on previous inspection was not there during this inspection. Some of the pits appear to be filled in; however, boulder piles were still on site. Overall it does appear that reclamation work has at least begun. Another inspection to verify the progress of the work should be completed when the snow melts.

Photos were taken to document site conditions.

Inspector's Signature



Inspection Date: December 5, 2013

Page 2 of 2

S/049/0050

